

## **T-ACE Instruction Manual**

For Safe Use

Thank you for your selection of Tsubaki Belt Tension Meter T-ACE.

• I Do not wet the product with water or oil nor give shock to it such as by dropping it. The product may fail.

- I Do not disassemble or modify the product. Such a practice may cause fire or electric shock.
- I Do not keep the product in places that are humid, hot or filled with dust.
- I When the product will not be used, remove the battery and keep the product in the case.
- I Do not bend the sensor microphone. To pull it out, hold the connector. Otherwise the product may fail.

List of Unit Mass

/ Danger Do not use the product when the belt is running. Otherwise, your hand may get caught.

(Measurement is possible only when the belt is at a stop.)

● PX tooth profile Unit: kg/m ● Trapezoidal ·							oidal tooth profile Unit: kg/m ● Urethane Unit: kg										it: kg/m						
Туре	Width (mm)	MASS	Туре	Width (mm)	MASS	Туре	Nominal Width	Width (mm)	MASS	Туре	Nominal Width	Width (mm)	MASS	Туре	Nominal Width	Width (mm)	MASS	Туре	Width (mm)	MASS	Туре	Width (mm)	MASS
P2M	4 6 10	0.006 0.008 0.014 0.013	UP14M	40 60 80	0.304 0.456 0.608 0.760	MXL	3.2 4.8 6.4 9.5	3.2 4.8 6.4 9.5	0.004 0.006 0.008 0.012	ххн	200 300 400 500	50.8 76.2 101.6 127.0	0.818 1.227 1.636 2.045	MXL	3.2 4.8 6.4	3.2 4.8 6.4	0.005 0.007 0.009	T2.5	3 5 7	0.005 0.008 0.011 0.015	AT5	10 15 25 50	0.038 0.057 0.095 0.190
P3M UP3M	10 15	0.022		120	0.912		12.7	12.7	0.016			127.0	2.010		025 031	6.4 7.9	0.015 0.019		5 10	0.016	AT10	25 50	0.170 0.340
P5M UP5M	10 15 25	0.041 0.062 0.103	DP3M	6 10 15	0.015 0.025 0.038	XL	025 031 037	6.4 7.9 9.5	0.017 0.021 0.026	DXL	025 031 037	6.4 7.9 9.5	0.012 0.015 0.018	XL	037 050 075	9.5 12.7 19.1	0.023 0.034 0.052	Т5	15 20 25	0.048 0.064 0.080	AT20	75 50 75	0.510 0.550 0.825
P8M	15 25 40 60	0.084 0.139 0.223 0.334	DP5M	10 15 25	0.038 0.058 0.096	L	050 050 075 100	12.7 12.7 19.1 25.4	0.035 0.048 0.073 0.097	DL	050 075 100	12.7 19.1 25.4	0.042 0.062 0.083		100 037 050 075	25.4 9.5 12.7 19.1	0.068 0.036 0.046 0.069	T10	15 20 25	0.075 0.100 0.125	DT5	5 10 15	0.012 0.024 0.036
P14M	40 60 80 100	0.393 0.589 0.786 0.982	DP8M	15 25 40 60	0.088 0.148 0.237 0.355	н	075 100 150 200	19.1 25.4 38.1 50.8	0.101 0.135 0.202 0.269	DH	075 100 150 200	19.1 25.4 38.1 50.8	0.084 0.112 0.169 0.225	L	100 150 200 050	25.4 38.1 50.8 12.7	0.091 0.146 0.194 0.068		50 75 25	0.250 0.375 0.180		20 15	0.047
UP8M	120 15 25 40 60	1.178 0.076 0.127 0.203 0.304	DP14M	40 60 80 100 120	0.417 0.626 0.835 1.043 1.252	ХН	300 200 300 400	76.2 50.8 76.2 101.6	0.635 0.953 1.270		300	/6.2	0.337	н	075 100 150 200 300 400	19.1 25.4 38.1 50.8 76.2 101.6	0.096 0.127 0.191 0.254 0.380 0.538	120	50 75	0.360 0.540	0110	20 25	0.106 0.132

## Basic formula

Tsubaki Belt Tension Meter T-ACE calculates the tension using the following formula:



$$F = \frac{1}{-2L} \sqrt{\frac{T}{W}}$$

•Belt tension

 $T = 4 \times W \times L^2 \times F^2$ 

	F: Frequency
T: Belt tension	Dp: Large pulley pitch diameter
L: Span length	dp: Small pulley pitch diameter
W: Belt unit mass	c: Distance between shafts

·Span length

 $L = \sqrt{C^2 - \frac{(Dp - dp)^2}{4}}$ 

Specifications						
Model	BDTM101					
Measuring range	0.1∼9999N, 30∼600Hz					
Belt span length	0.001~9.999m					
Unit mass	0.001~9.999kg/m					
Working temperature	−10~60°C					
Power supply	Dry cell (AAA) x 4 pieces					
Mass and dimensions	160 g (main unit)					
	162 long x 61.6 wide x 30 thick in mm					
Accessories	Sensor microphone,					
	dry cells (AAA x 4 pieces), carrying case					

times Even if the mounting tension is adequate, the vibration frequency may be out of the

measurable range of the product depending on a combination of measuring conditions used.

(A particular attention is required when the span length exceeds 1 m.)

	[Description	of the Functior
	1)LCD screen	<ol> <li>Battery… Lights up when the cells need to be replaced.</li> <li>Measurement result… Shows the measurement result converted to belt tension.</li> <li>Unit… Shows the measurement result unit in N or Hz.</li> <li>SPAN/MASS… Shows measuring conditions. Flashes during condition setting.</li> </ol>
	Dennen mienenhane	<ul> <li>b) Memory… Shows the applicable MEM no. (no. 01~10)</li> <li>6) S mark… Lights up during measurement.</li> </ul>
	3 START button	When this is pressed to start measurement, the <b>S</b> mark will appear on the LCD screen. Then bring the microphone close to the belt and flip it with fingers to take measurement
	4)N/Hz select button 5)SPAN/MASS buttons	Changes over measurement results between N and Hz display. When these buttons are pressed, the meter enters the measuring condition input mode
5		and the display flashes. • SPAN •••• Belt span length(m) • MASS •••• Belt unit mass (kg/m)
		Using the ten-key pad, enter a numeric value and press the button again. Then the value is accepted.
	6)MEM(Memory) Button 7)Ten-key Button	Use this button to store measuring conditions or call stored conditions. Use this pad to enter measuring conditions.
	8ON/OFF Button	Press this button to turn on/off the power. If the meter is not operated at all for three minutes, the power is turned off automatically.

## [Operating Procedure]

Procedure	Display Status
<ol> <li>Power on the meter.</li> <li>Hold the ON/OFF button pressed for one second or longer.</li> </ol>	Ø
<u>Cautions</u> ) <u>The initial display is as follows; measurement result = 0, unit = Hz and MEM no. = blank.</u> When the meter is used the second time and thereafter, the previous conditions and measurement results are shown.	Ο
2. Enter measuring conditions. Exa.) SPAN 0. 325m MASS 0. 139kg∕m	Hz
<ul> <li>Press the SPAN button for about one second. The SPAN display part flashes and the meter is ready for entry of a numeric value.</li> <li>The initial value is "0.100". (<i>Display status</i>)</li> </ul>	SPAN , 0. 100 (m) MASS 0. 100
<ul> <li>Using the ten-key pad, enter a numeric value. The decimal point is fixed and needs not be entered.</li> <li>Figures are entered from the left side place.</li> <li>If you entered a wrong figure, enter all places once, and then re-enter correct figures starting with the left place.</li> </ul>	(kg/m)
0+3+2+5	
<ul> <li>After having entered a numeric value, press the SPAN button again for about one second. The value is stored.</li> <li>The display changes from flashing to lit status. (You will hear a sound "pi".)</li> </ul>	
• Enter a value to MASS similarly. (For the belt unit mass, see the List of Unit Mass.)	0
<ul> <li>Up to 10 measuring conditions can be stored in memory. After entering a condition to store, press the MEM button for one second or longer. Then the memory display part flashes.</li> <li>Then each time the button is pressed quickly, the display changes as MEM no.01 =&gt; 02 =&gt;.</li> <li>Select a number to store and press the MEM button again for one second or longer.</li> </ul>	Hz
Then the condition is stored. ( <i>Display status</i> (2)	SPAN 0. 325
<ul> <li>3. Start measurement.</li> <li>Select a unit to show measurement results by pressing the N/Hz button.</li> </ul>	(m) MASS 0. 139
<ul> <li>After pressing the START button, bring the microphone close to the belt and flip the belt with fingers and take measurement.</li> <li>When the measurement has been completed, you will hear a sound "pi" and the measurement result is shown. (Display status(3))</li> </ul>	
• While the mark $\blacksquare$ is being shown, measurement can be repeated as many times as necessary.	
<ul> <li>To use the conditions stored in memory, press the MEM button quickly and select the MEM no. to use. Then the stored conditions are shown in SPAN and MASS.</li> </ul>	3
<ul> <li>4. End.</li> <li>• To end the measurement, hold the ON/OFF button pressed for two seconds or longer.</li> </ul>	150
If the meter is not operated at all for three minutes, the power is automatically turned off.	S N
<u>Cautions)</u> The following are operation errors and a sound "pi" will be issued:	SPAN 0. 325
<ul> <li><u>A button other than those on the ten-key pad is pressed in the input mode.</u> When a numeric value of SPAN and MASS is flashing (meaning the input mode).</li> </ul>	(m)
the operation of buttons other than those on the ten-key pad is not accepted (except for the ON/OFF button). Operate them after ending the input mode.	(kg/m)
<ul> <li><u>A value "0.000" is entered to SPAN and MASS.</u></li> <li><u>If SPAN and MASS are set to "0.000", the input mode cannot be ended.</u></li> </ul>	
<ul> <li>The ten-key pad is operated in modes other than the SPAN and MASS input mode (flashing).</li> </ul>	